



Photo 5: Literider Model Stroller




Photo 6: Folding hinge location on the side of the stroller posing a hazard.